



New Product Information

*TCC VALVE REPLACEMENT
for P1870 / P1728 Code
(No Reaming Required)*



Part# A74741CB

Teckpak-Fitzall now has a redesign of their popular A74741QA valve used to fix the 1870 Code in the earlier 4L60E transmissions. The new replacement valve (**A74741CB**) is for use in '04-up GM RWD vehicles with 4L60E, 4L65E & 4L70E transmissions that utilize the CANBUS control systems.

Like Teckpak-Fitzall's other 1870 Code fixes, the **A74741CB** uses O-rings to seal the bore and does not require reaming.

The new valve allows the converter to unlock if the PWM drops to a very low duty cycle, while still sealing the worn valve bore.