



New Product Information

TRANSMISSION PAN REPAIR NUT
for 5R55S & 5R55W



T16494A

When you are removing the filler plug from the bottom of the transmission pan, it can break loose and spin the bradded nut causing leakage.

DON'T THROW THE PAN AWAY!

Use Teckpak-Fitzall **(T16494A)** pan repair nut.

It also saves those pans where the threads are stripped!

NOTE: Mounts inside the transmission pan.